



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18th STREET, SUITE 300
DENVER, CO 80202-2466
Phone 800-227-8917
<http://www.epa.gov/region08>

SDMS Document ID



2029753

Ref: 8EPR-SR

July 29, 2005

HARVEY JOHN KOSIK
7152 E 74TH PL
COMMERCE CITY CO 80022

RE: 4683 BALDWIN CT

Dear HARVEY JOHN:

The United States Environmental Protection Agency (EPA) has tested your property for arsenic and lead soil contamination as part of the Vasquez Boulevard/Interstate 70 (VB/I-70) Superfund Site. **Concentrations of Arsenic and/or lead found in your soil are high enough for your property to qualify for the removal action EPA is performing this year.**

<u>ADDRESS</u>	<u>EPA Cleanup Level</u>
Lead	
897 parts per million (ppm)	above 400 ppm
Arsenic	
16 ppm	above 70 ppm

EPA would like to remove the top layer of soil from your yard and replace it with clean soil. EPA will then re-landscape your yard to a condition similar to original. ***All work will be performed by EPA for free. EPA requires your consent to proceed as soon as possible.*** An Access Agreement that will allow the EPA to perform the soil removal work accompanies this letter. ***I strongly encourage you to sign this agreement and mail it back to the following address:***

US EPA – VB/I-70 Project Site
Attention: Victor Ketellapper
10 East 55th Avenue
Denver, Colorado 80216

Your property will be scheduled for soil removal provided we promptly receive the signed Access Agreement with a telephone number where you can be contacted. EPA will coordinate the soil removal activity with you to reduce any inconvenience to you. Upon completion of the cleanup, EPA will issue a letter stating that your property has been cleaned and that no further action is necessary.

Once the attached access agreement has been received, representatives of EPA will contact you to discuss the removal of contaminated soil from your property. In the meantime, if you have further questions regarding the removal of contaminated soil at your property, please contact us at (303) 487-0377.

Sincerely,

Victor Ketellapper
Remedial Project Manager
United States Environmental Protection Agency (US EPA)



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8

Victor Ketellapper

Phone 800-227-8917

<http://www.epa.gov/region08>

CONSENT FOR ACCESS TO PROPERTY

Name: HARVEY JOHN KOSIK
(or current property owner)

Location of Property: 4681 BALDWIN CT

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having ~~unassisted~~ ^{my escorted} access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfund), 42 U.S.C. § 9601 *et seq.*

Harvey Kosik
Printed Name

303-472-6770
Phone Number

Harvey Kosik
Signature

6-21-05
Date



Printed on Recycled Paper

4681 Baldwin



1 = 5'

6/15/05


SK + B

<u>Area</u>	<u># Grids</u>	<u># Samples</u>
1	24	7
2	34	10
3	<u>42</u>	12
	100/	
	30 = 3.33	

G A VB.4681.BA.01 1615

O □ VB.4681.BA.02 1620

Y ★ VB.4681.BA.03 1625



Total ARSENIC

Method SW6010B

Sample Results

Lab Name: Paragon Analytics

Client Name: URS Operating Services, Inc.

Client Project ID: VB & I-70 30505

Work Order Number: 0506269

Reporting Basis: Dry Weight

Prep Method: SW3050B

Final Volume: 100 ml

Matrix: SOIL

Result Units: mg/kg

Client Sample ID	Lab ID	Date Collected	Date Prepared	Date Analyzed	Percent Moisture	Dilution Factor	Result	Reporting Limit	Flag	Sample Aliquot
VB-3562-HI-01	0506269-1	06/15/2005	07/06/2005	07/12/2005	11.5	1	9.6	6.6		1.02 g
VB-3562-HI-02	0506269-2	06/15/2005	07/06/2005	07/12/2005	10.8	1	6.7	6.7		1 g
VB-3562-HI-03	0506269-3	06/15/2005	07/06/2005	07/12/2005	11.4	1	11	6.8		1 g
VB-3260-RA-01	0506269-4	06/15/2005	07/06/2005	07/12/2005	12.3	1	6.7	6.7	U	1.02 g
VB-3260-RA-02	0506269-5	06/15/2005	07/06/2005	07/12/2005	10.9	1	6.5	6.5	U	1.04 g
VB-3260-RA-03	0506269-6	06/15/2005	07/06/2005	07/12/2005	11.6	1	6.8	6.8	U	1 g
VB-3750-MA-01	0506269-7	06/15/2005	07/06/2005	07/12/2005	5.2	1	6.3	6.3	U	1 g
VB-3750-MA-02	0506269-8	06/15/2005	07/06/2005	07/12/2005	5.4	1	6.3	6.3	U	1 g
VB-3750-MA-03	0506269-9	06/15/2005	07/06/2005	07/12/2005	6.5	1	8.4	6.4		1 g
VB-4681-BA-01	0506269-10	06/15/2005	07/06/2005	07/12/2005	3.7	1	13	6.2		1 g
VB-4681-BA-02	0506269-11	06/15/2005	07/06/2005	07/12/2005	5.9	1	16	6.3		1.02 g
VB-4681-BA-03	0506269-12	06/15/2005	07/06/2005	07/12/2005	3.5	1	14	6		1.04 g
VB-5041-AD-01	0506269-13	06/16/2005	07/06/2005	07/12/2005	11.1	1	32	6.7		1 g
VB-5041-AD-02	0506269-14	06/16/2005	07/06/2005	07/12/2005	12.7	1	39	6.9		1 g
VB-5041-AD-03	0506269-15	06/16/2005	07/06/2005	07/12/2005	14.5	1	29	7		1 g

Comments:

1. ND or U = Not Detected at or above the client requested detection limit.

Data Package ID: *ip0506269-1*

Date Printed: Thursday, July 14, 2005

Paragon Analytics

LIMS Version: 5.201A

Page 1 of 2

Total LEAD
Method SW6010B
Sample Results

Lab Name: Paragon Analytics
 Client Name: URS Operating Services, Inc.
 Client Project ID: VB & I-70 30505
 Work Order Number: 0506269
 Reporting Basis: Dry Weight
 Prep Method: SW3050B

Final Volume: 100 ml
 Matrix: SOIL
 Result Units: mg/kg

Client Sample ID	Lab ID	Date Collected	Date Prepared	Date Analyzed	Percent Moisture	Dilution Factor	Result	Reporting Limit	Flag	Sample Aliquot
VB-3562-HI-01	0506269-1	06/15/2005	07/06/2005	07/12/2005	11.5	1	240	5.5		1.02 g
VB-3562-HI-02	0506269-2	06/15/2005	07/06/2005	07/12/2005	10.8	1	270	5.6		1 g
VB-3562-HI-03	0506269-3	06/15/2005	07/06/2005	07/12/2005	11.4	1	360	5.6		1 g
VB-3260-RA-01	0506269-4	06/15/2005	07/06/2005	07/12/2005	12.3	1	94	5.6		1.02 g
VB-3260-RA-02	0506269-5	06/15/2005	07/06/2005	07/12/2005	10.9	1	71	5.4		1.04 g
VB-3260-RA-03	0506269-6	06/15/2005	07/06/2005	07/12/2005	11.6	1	79	5.7		1 g
VB-3750-MA-01	0506269-7	06/15/2005	07/06/2005	07/12/2005	5.2	1	240	5.3		1 g
VB-3750-MA-02	0506269-8	06/15/2005	07/06/2005	07/12/2005	5.4	1	260	5.3		1 g
VB-3750-MA-03	0506269-9	06/15/2005	07/06/2005	07/12/2005	6.5	1	260	5.3		1 g
VB-4681-BA-01	0506269-10	06/15/2005	07/06/2005	07/12/2005	3.7	1	1600	5.2		1 g
VB-4681-BA-02	0506269-11	06/15/2005	07/06/2005	07/12/2005	5.9	1	520	5.2		1.02 g
VB-4681-BA-03	0506269-12	06/15/2005	07/06/2005	07/12/2005	3.5	1	570	5		1.04 g
VB-5041-AD-01	0506269-13	06/16/2005	07/06/2005	07/12/2005	11.1	1	88	5.6	E	1 g
VB-5041-AD-02	0506269-14	06/16/2005	07/06/2005	07/12/2005	12.7	1	100	5.7		1 g
VB-5041-AD-03	0506269-15	06/16/2005	07/06/2005	07/12/2005	14.5	1	87	5.8		1 g

Comments:

1. ND or U = Not Detected at or above the client requested detection limit.

Data Package ID: *ip0506269-1*